

Taurus Release 1.01.06 Notes

Release Importance:

Priority 1. Important Update. Strongly Recommended - Perform As Soon As Possible.
Update affects data availability in Taurus store.

Software Improvements:

- Improved timing system performance over wide temperature range
- Eliminated small data gaps caused when operating Taurus in Buffered mode and GPS in automatic mode.
- Power management and improvements to low-level watchdog performance
- Improved NP to NMXP (NAQS) re-transmission operation reducing time to complete re-tx requests.

New Features:

No new features. Maintenance Release only

Known Issues:

This release contains the following operational behaviors or minor bugs planned to be addressed in future maintenance releases.

Issue	Description and Workaround
Switch to Buffered Mode	When changing the Taurus from Communications mode to Buffered mode, the Taurus stays in Communications Mode. Workaround: On shutdown page, select “Turn-Off Display” to ensure units switches to Buffered Mode
Time-series Download	Occasionally attempting to download time-series data results in “The Store is Closed” message. Workaround: Close external browser and re-open.
Status Page – No Data Available Message	"No Data Available" showing on the Current status page, while data is updated on the Waveform and Sensor pages. Workaround: Close the external browser and re-open.

End of Notes

- | | |
|---|-----------------------------------------------------------------------------------------------|
| ✓ | Priority 1. Important Update. Strongly Recommended - Perform As Soon As Possible |
| □ | Priority 2. Performance Update. Highly Recommended – Perform to realize improved performance. |
| □ | Priority 3. Routine Update. Perform as Time Permits |